

SECRET

Approved For Release 2001/08/26 : CIA-RDP33-02415A000600050009-0
USAF Declass/Release Instructions On File

ATTG Reg 10-2

4. Redeployment loading was complicated by fork lift failure, but completed . . . etc . . . etc . . .

B. PROBLEMS/RECOMMENDATIONS

1. PROBLEM: AGE not available for four hours after arrival.

RECOMMENDATION: Permit [REDACTED] representative to accompany survey 25X1A team so as to insure unit needs are positively established.

2. PROBLEM: No new filters available for JPTS truck.

RECOMMENDATION: Authorize inclusion of filter element in Phase I POL kit.

3. OBSERVATION: The support aircraft crew arrived without artic gear because of last minute assignment to the mission. Gear provided by [REDACTED] 25X1A to the extent possible.

4. etc . . . etc . . .

Roger L. Cooper

ROGER L. COOPER, Colonel, USAF
Commander

SECRET